




**7800** Wipe Out is a medium evaporating solvent based wax and grease remover. It can also be used to remove tar and road film and is excellent for cleaning bare metal. Safe for use on all cured lacquer, enamel, urethane, clear coat and primed surfaces.

### DESCRIPTION

**7800-1 – Wipeout Surface Prep GALLON**  
**7800-4 – Wipeout Surface Prep QUART**  
**7800-5 – Wipeout Surface Prep 5 GALLONS**  
**7800-A – Wipeout Surface Prep 19 oz. AEROSOL**

### SURFACE PREPARATION / APPLICATION



- 1) Using a clean lint free cloth, apply adequate amounts of 7800 to the area to be cleaned, one panel at a time.
- 2) Allow some time for 7800 to work at dissolving any contamination and or surface residue.
- 3) While the panel is still wet, thoroughly wipe dry with a clean cloth.
- 4) Repeat the above if necessary.

### TECHNICAL DATA

Wipeout - Surface Prep: 7800

#### **V.O.C.**

6.30 lbs per gallon/755 grams per liter

#### **FOR INDUSTRY USE ONLY Read MSDS Before Use**

Before opening the packages, read all warning labels. Follow all precautions. The material is designed for application only by professionally trained personnel using proper equipment under controlled conditions, and is not intended for sale to the general public **SEE MSDS AND PRODUCT LABELS FOR ADDITIONAL SAFETY INFORMATION**

